

Request List Report

3/25/2019

JANUARY 2019 COMPLETED

3:41 PM

Request #	Category	Address	Status
Created	Problem	Cross Street	
19-000003	Public Works	6703 SULLIVAN RD	WO Completed
1/2/2019	Traffic Sign Maintenance		
STREET SIGN DOWN, POST IS GOOD, RE-INSTALL			
19-000004	Public Works	12735 MUSTANG AVE	WO Cancelled
1/2/2019	Storm Drain Repair		
SINK HOLE IN FRONT			
CALL HOMEOWNER FOR EXACT LOCATION			
19-000005	Public Works	14251 CRYSTAL DR	WO Completed
1/2/2019	Draining Maintenance		
REMOVE DEBRIS FROM SIDE AND REAR CANALS ICE CHEST, HUGE LIMB,BABY MATTRESS BOARDS			
19-000006	Public Works	11186 HENSON DR	WO Completed
1/2/2019	Backfill/Dressup		
BACKFILL			
19-000007	Public Works	6848 MICAH'S WAY	WO Completed
1/2/2019	Backfill/Dressup		
BACKFILL HOLE NEXT TO BOX			
19-000008	Public Works	0 BEAUFORT DR	WO Completed
1/3/2019	Draining Maintenance		
cleaned the cross culvert on beaufort dr			
19-000009	Public Works	13642 MARLIN AVE	WO Completed
1/3/2019	Backfill/Dressup		
BACKFILL			
19-000010	Public Works	0 MORGAN MEADOW	WO Completed
1/3/2019	Pot Hole Patching		
POT HOLES @ SAGEFIELD AND MORGANFIELD			
19-000013	Public Works	0 HAMPTON VILLAGE	WO Completed
1/3/2019	Pot Hole Patching		
POT HOLES AT ENTRANCE AND EXIT OF SOBDIVISION			
19-000014	Public Works	9748 OVERWOOD DR	WO Completed
1/3/2019	Draining Maintenance		
DUG DITCH NOW YARD IS A POND			
19-000015	Public Works	0 CENTRAL WOODS AVE	WO Completed
1/4/2019	Litter Control		
PICK UP TRASH DUMPED IN/ALONG ROAD			
19-000017	Public Works	16955 J L FAIRCHILD RD	WO Completed
1/4/2019	Culvert Clean Out		
CLEAN OUT CULVERTS			
19-000018	Public Works	0 COUNTRY RD	WO Completed
1/4/2019	Culvert Clean Out		
ENTRANCE COUNTRY RD @ FRENCHTOWN CULVERTS CLOGGED-WATER GOING OVER ROAD IN HEAVY RAIN EVENT			
19-000020	Public Works	0 CRYSTAL DR	WO Completed
1/4/2019	Traffic Sign Maintenance		
STOP SIGN DOWN CORNER OF CRYSTAL AND LOCKRIDGE			
19-000021	Public Works	0 THIBODEAUX RD	WO Completed
1/4/2019	Pot Hole Patching		
POT HOLE THIBODEAUX RD @ PLANCHET RD			
19-000022	Public Works	0 LOVETT RD	WO Completed
1/7/2019	Pot Hole Patching		
POT HOLE SULLIVAN TOWARDS JOOR			

Request List Report

3/25/2019

JANUARY 2019 COMPLETED

3:41 PM

Request #	Category	Address	Status
Created	Problem	Cross Street	
Comments for Work Order			
19-000023	Public Works	0 DENHAM RD	WO Completed
1/8/2019	Pot Hole Patching		
POTHOLES NEAR THE ENTRANCE OF GREYSTONE DR			
19-000024	Public Works	10611 DURMAST DR	WO Completed
1/9/2019	Backfill/Dressup		
BACKFILL			
19-000025	Public Works	11090 GATE WAY DR	WO Completed
1/9/2019	Backfill/Dressup		
SPREAD SPOILS FROM PREVIOUSLY DUG DITCH			
19-000026	Public Works	13565 HOOPER RD	WO Completed
1/9/2019	Miscellaneous		
DELIVERED SANDBAGS TO FIRE DEPT.			
19-000028	Public Works	0 SHADY PARK DR	WO Completed
1/9/2019	Litter Control		
REMOVE PILE OF TRASH ON R O W			
19-000029	Public Works	0 FRENCHTOWN RD	WO Completed
1/9/2019	Tree Removal		
I NEED PICTURES.			
LOW HANGING LIMB OVER THE ROAD			
19-000030	Public Works	0 PLANCHET RD	WO Cancelled
1/9/2019	Tree Removal		
TREE FELL AND IS LEANING AGAINST THE GUARD RAIL, TOP OF THE TREE IS LYING ON THE BRIDGE IN BETWEEN PLANCHET AND THRUWAY			
SAME AS 19-000029			
19-000032	Public Works	16348 CHEVERNT AVE	WO Completed
1/9/2019	Tree Removal		
TREE DOWN IN BEAVER BAYOU @ FRENCHTOWN			
19-000033	Public Works	12745 MUSTANG AVE	WO Completed
1/9/2019	Backfill/Dressup		
NEEDS BACKFILL BY DRIVEWAY			
19-000036	Public Works	0 WAX RD	WO Completed
1/9/2019	Not In Scope		
CALLED ARMCO @ 262-1116-BOTTOM BULB OF FLASHING LIGHT IS OUT NEEDS REPLACING-MELISSA WILL ALERT TODD AND CASEY			
19-000040	Public Works	0 VILLAGE GREEN DR	WO Completed
1/10/2019	Pot Hole Patching		
POT HOLE VILLAGE GREEN @ ASHTON			
19-000042	Public Works	0 WAX RD	WO Completed
1/10/2019	Pot Hole Patching		
MULTIPLE POT HOLES ON OLD WAX RD			
19-000043	Public Works	14446 JOOR RD	WO Completed
1/10/2019	Off Road Drainage		
NEEDS HELP REMOVING DEBRIS FROM UNDER BRIDGE IN REAR			
19-000044	Public Works	9626 SAGEFIELD DR	WO Completed
1/11/2019	Backfill/Dressup		
BACK FILL IN DRIVEWAY FOR PREVIOUS REPAIR			
19-000045	Public Works	17232 ASHTON AVE	WO Completed
1/11/2019	Draining Maintenance		
DUG SIDE DITCH NOW WATER IS BACKING UP IN BACKYARD NOT SURE WHERE THE WATER IS COMING FROM			

Request List Report

3/25/2019

JANUARY 2019 COMPLETED

3:41 PM

Request #	Category	Address	Status
Created	Problem	Cross Street	
Comments for Work Order			
19-000046	Public Works	16727 TENIEYA AVE	WO Completed
1/11/2019	Backfill/Dressup		
BACKFILL FOR PREVIOUSLY REPAIR DRIVEWAY			
19-000047	Public Works	18367 EDNIE LN	WO Completed
1/11/2019	Backfill/Dressup		
DRIVEWAY BACKFILL			
19-000048	Public Works	10258 LA JOLLA CT	WO Completed
1/11/2019	Not In Scope		
TEMP ORANGE FENCING AROUND PERIMETER OF POOL			
TRACK TIME AND MATERIALS TO BILL HOMEOWNER			
19-000051	Public Works	13642 MARLIN AVE	WO Completed
1/11/2019	Backfill/Dressup		
BACKFILL			
19-000052	Public Works	15047 GLENN DR	WO Completed
1/11/2019	Backfill/Dressup		
BACKFILL AROUND CATCH BASIN			
19-000055	Public Works	7912 JOOR RD	WO Completed
1/11/2019	Miscellaneous		
RESURFACED THE ROAD AND HAS LEFT BLACKTOP EVERYWHERE			
19-000059	Public Works	0 CENTERRA CT	WO Completed
1/11/2019	Pot Hole Patching		
POT HOLES ENTIRE ROAD			
19-000062	Public Works	0 RAMBLING OAKS AVE	WO Completed
1/14/2019	Traffic Sign Maintenance		
STOP SIGN DOWN RAMBLING OAKS AVE @ SPANISH OAK			
19-000063	Public Works	0 PERNECIA AVE	WO Completed
1/14/2019	Traffic Sign Maintenance		
TRIM TREES BACK TO MAKE STOP SIGN VISIBLE PERNECIA @ YATASI			
19-000066	Public Works	6131 LANDMOR DR	WO Completed
1/15/2019	Backfill/Dressup		
ASPHALT BACKFILL			
19-000068	Public Works	0 GURNEY RD	WO Completed
1/16/2019	Traffic Sign Maintenance		
STREET SIGN BENT			
19-000070	Public Works	15315 CHARLESTON DR	WO Completed
1/17/2019	Off Road Drainage		
REMOVE DEBRIS FROM SIDE DITCH			
19-000071	Public Works	12524 PECOS AVE	WO Completed
1/17/2019	Pot Hole Patching		
BIG HOLE IN ROAD IN FRONT OF ADDRESS			
19-000072	Public Works	14612 CRYSTAL DR	WO Completed
1/18/2019	Off-Road Weedeating/Cleanup		
CLEAN REAR DITCH FROM BEHIND 14622 CRYSTAL DR TO 14408 CRYSTAL DR.			
19-000073	Public Works	0 MCCULLOUGH RD	WO Completed
1/18/2019	Pot Hole Patching		
POT HOLE-COMING FROM JOOR PASSED WOODROW KERRLN			
19-000074	Public Works	12726 LARIAT AVE	WO Completed
1/18/2019	Backfill/Dressup		
LIMESTONE BACK FILL IN DRIVEWAY			

Request List Report

3/25/2019

JANUARY 2019 COMPLETED

3:41 PM

Request #	Category	Address	Status
Created	Problem	Cross Street	
19-000075	Public Works	0 WISTERIA LAKES DR	WO Completed
1/18/2019	Pot Hole Patching		
POT HOLES IN FRONT OF ADDRESSES 14500 & 14710 WISTERIA LAKES DR			
19-000076	Public Works	0 BRENNEN DR	WO Completed
1/18/2019	Pot Hole Patching		
POT HOLES THROUGHOUT ENTIRE SUBDIVISION			
19-000078	Public Works	0 N EISWORTH AVE	WO Completed
1/22/2019	Pot Hole Patching		
CALL BEFORE GOING			
POT HOLES THROUGHOUT SUBDIVISION			
CURB MISSING CHUNKS IN AREAS			
SEAL CRACKS BEFORE ROAD DAMAGE OCCURS			
19-000080	Public Works	17610 VILLA LAKES AVE	WO Completed
1/22/2019	Miscellaneous		
PUT RYE GRASS DOWN TO CONTROL EROSION			
19-000081	Public Works	17422 LAKE VISTA DR	WO Completed
1/22/2019	Backfill/Dressup		
REMOVE CONCRETE BACK FILL WITH 610 LIMESTONE			
19-000082	Public Works	16382 HOOPER RD	WO Completed
1/22/2019	Not In Scope		
huge pump pumping gallons of water into the ditch off of the property of the construction			
dirt trucks coming out of the site flipped while fully loaded with dirt and it was dumped into the ditch on "our side " at the complex			
19-000083	Public Works	0 WOODLAND VIEW DR	WO Completed
1/23/2019	Pot Hole Patching		
POT HOLE ON WOODLAND VIEW AVE			
19-000085	Public Works	0 EMPRESS DR	WO Completed
1/25/2019	Pot Hole Patching		
patch up pot hole on empress @ landmor			
19-000088	Public Works	0 NORWAY PINE DR	WO Completed
1/25/2019	Backfill/Dressup		
BACK FILL RUTS FROM FIRETRUCKS GETTING STUCK IN YARD			
NORWAY PINE AND FIR			
19-000089	Public Works	11741 N MILSTEAD PL	WO Completed
1/25/2019	Backfill/Dressup		
DRIVEWAY SETTLING NEEDS BACKFILL			
19-000096	Public Works	0 LANDMOR DR	WO Completed
1/28/2019	Storm Drain Repair		
STORM DRAIN REPAIR AT CORNER OF LANDMOR @ EMPRESS			
19-000105	Public Works	0 BROWN RD	WO Completed
1/29/2019	Pot Hole Patching		
SHOULDER EROSION-EBR PLACED LIGHTED BARRICADES ALONG ROAD			